

# Mounting instructions



## AIRCELL®5

BNC-Male, crimp / item. no.: 772100



1  
Cut off the cable end at right angles. Push the crimp sleeve over the cable end. Remove 16mm of the outer jacket.



2  
Twist the copper braid at right angles.



3  
Remove 4mm of the copper foil with a knife.



4  
Remove 4mm of the foamed dielectric.



5  
Place the inner pin on the conductor and solder / crimp.



6  
Push the end of the cable thus prepared up to the Stop (click) in the connector housing.



7  
Cut the copper braid with the side cutter  
And move the crimp sleeve forward



8  
Crimp the crimp sleeve with the crimping plier, so that the copper braid is clamped between the plug housing and the crimping sleeve.